ST-NXP Wireless

HAMAMATSU THEMOS Mini Evaluation

Involved laboratories: CPG Agrate, RCCAL Rousset, Grenoble FA Lab

WMM, C&P Failure Analysis / GNB Failure Analysis Lab EUFANET


Optical Localization Techniques Workshop

26 & 27/01/09

Company Confidential / Jean Roux – Hamamatsu France

Outlines


- Introduction of thermal lockin
- Equipment short introduction
- Image Interpretation : Emissivity issue & Temperature calibration
- Casis studies on various processes , sample types and failures
- Summary : Thermal Imaging as a contribution to FA root cause extraction with EMMI and TLS.
- X ray & Thermal imaging combination.



HAMAMATSU

Copyright C Hamamatsu Photonics K.K. All Rights Reserved.


1. Principle of "Thermal Lockin" analysis



An amplitude image and a phase image are built by conducting lock-in analysis spatially.



Digital Lock-in for laser and thermal scan application



Digital lock-in with sampled image ST-NXP Wireless

WMM, C&P Grenoble FA LAB

Company Confidential

2. Features of the Lock-in method

- 1. Thermal lock-in analysis reduces noise and drastically improves the S/N ratio.
 - The kind of noise
 - Random noises, such as fluctuation of heat.
 - The background ingredient by the heat rise of the sample itself.
 - The pattern outline ingredient by vibration.

2. Pinpointing of an exothermic part is possible.

- Predominance point
 - Solution of the equalization problem by diffusion of heat.
 - Solution of detection mistake problem by the difference of emissivity.

3. Domination of phase information


- Improvement of weak thermal emission detection from feature that doesn't depend on thermal emission strength..
- It is possible to extract thermal emission of target timing.
- The response characteristic of thermal emission is understood.



2-2-1. Specific of heat source points by removal of

thermal diffusion.

Result of changing power supply modulation frequency.



Conventional method: 40seconds


Thermal lock-in method: 1Hz

Thermal lock-in method: 20Hz

The dispersion of heat is suppressed by raising the modulation frequency, and the identification of the thermal source points is facilitated.




2-2-2. Even if emissivity is different, the thermal emission source points can be specified.





2-3-1. It becomes easy to detect week thermal emission by phase information.




Thermal lock-in : Amplitude

Thermal lock-in : Phase

Week thermal emission was not able to be detected in the amplitude image, but it was able to be detected from the phase image.

2-3-2. Extraction of target data according to timing.






WMM, C&P Grenoble FA LAB

Company Confidential

2-3-3. The response characteristic of thermal emission

is understood.

Thermal lock-in : phase image



1Hz

2Hz


10Hz

The heat response characteristic can be recognized by changing the frequency of thermal lock-in.




1. Equipment Introduction






InSb camera 320x240 pixels Noise Equivalent Temperature Difference < 25 mK at 30°C (typ) Resolution 0.8 µm (at 20x lens NA=0.4) Manual revolver & xyz stage MWIR lens 0.8x, 4x, 15x / Probing lens 5x Illumination for probing Vibration isolation table Simplified HPK prober **ST-NXP Wireless**

B. Lenses description



2. Image Interpretation

Higher to Lower Temperatures, BUT comparison is possible for materials with same emissivity.







3. Acquired Images

A. <u>Thermal Mapping</u>

Techno : CMOS090





Lock in 0.4Hz Amplitude

Lock in 0.4Hz Phase


 A tester is used to loop a functional pattern during thermal acquisition.

- Temperature is higher on the edge of die close to areas from bandgap to PLL.
- Heat signature is almost the same between the 2 lots, just a little higher on fast lot.


NXP Wireless

Techno : XXX

Sample 1: unit is running, heating phase




Sample 2: unit is stopped, cooling phase



- Thermal mapping acquisition is done with an application board.
- Package is not decapsulated.
- Feedback from our internal requestor:
- There is no thermal camera matching our needs, temperature value measurement with an accuracy of +/-5°C.
- Option available Q2/09

B. Latch-Up issue / Techno : XXX




Latch-up – clamp 100mA

No latch-up


 Hot spot in a specific pad just before triggering the Latch Up (this pad is the source which delivers the current sunk on C1NI bloc). Then a very intense hot spot is detected on ESD protection structure once the LU is triggered.


C. Leakage issue / Techno : XXX




- Leakage on Vdig 10 µA vs 1 µA for a Ref.
- Obirch analysis done with no abnormal signature.
- Thermal analysis shows hot spots close to Vdd pads.
- → Damages are seen on die edge probably due to a bad sawing.


Through Silicon Vias (TSV) process overview








- Leakage on Vana 1 mA vs 1.5 µA for a Ref.
- Obirch analysis done with no abnormal signature.
- Thermal analysis shows hot spots at the bottom right corner of the die close to Vana pad.
- \rightarrow Damages are seen on die edge probably due to a bad sawing.





D. EOS reproduction / Techno : XXX

Amplitude




- Leakage 0.5V/100mA after stress.
- Localization with both OBIRCH & Thermal analyses.
- Interest of phase information, small spot is seen in amplitude but the area is heating at the same time compare to big spot area. → same cells damaged.





 The 'CLAMP_1V0_ANA' structures on VTT are damaged: silicon melting interconnect blow-up (contacts fused) and gate oxide breakdown.







- OBIRCH & Thermal signatures are not localized in a "specific" structure and are quite diffuse: an issue under the active area of the die is suspected (back-end / bump level).
- The failure modes observed are voids in underfill, a solder extrusion and a metal migration in bump.

WMM, C&P Grenoble FA LAB

Company Confidential

ILLESS






- Charger issue: fast charger connection up to 16V is breaking the phones.
- The movie capability of Themos mini was used to locate easily the failure. Then photos are generated when the fail is triggered.
- Emission localization was performed and emission is found above the driftswitch when the current is latched.

SI-NXP WIREIESS

Emission




- Short 0.1V / 1.25mA.
- Good result BS vs FS (0.8x & 4x), Better FS result @ 15x (Top layer level issue suspected)
- Two thermal spots localized, less noised than OBIRCh signature.
- Parasitic trench filled with metal creating a short between M5 & M4 layers.
 WMM, C&P Grenoble FA LAB
 Company Confidential

H. Short - CMP M5 suspected / Tecno : XXX

Amplitude


OBIRCH




- Short 0.05V / 3.54mA.
- Good result BS vs FS (@ 0.8x => 15x)
- Lock-In has a real impact on localization
- Two thermal spots localized in comparison of OBIRCh signature.
- CMP issue is confirmed.




Amplitude





OBIRCH

- Short 0.05V / 5.57mA.
- Good result BS vs FS (@ 0.8x => 15x)
- Lock-In has a good impact on localization
- One thermal spots localized in comparison of OBIRCh signature.




- Even if no spot was visible either with OBIRCH or EMMI, an accurate backside visual inspection performed with InGaAs EMMI detector showed a burning on the active area in the failing pad.
- By thermal camera equipment we managed to see an anomalous dissipation of power in the area of the failing pad.
- We then proceeded by quick de-processing to reach the active area, finding out the final confirmation of the presence of the burning.

WMM, C&P Grenoble FA LAB

Company Confidential

InGaAs image



4. Summary

Process	Sample type	Problem	EMMI	OBIRCH	THERMAL
ххх	Package	Good	NA	NA	Mapping
ххх	Package	Good	NA	NA	Mapping
ххх	Package	Latch-up	No (too many spots)	No	Yes
ххх	Package	Leakage	No	No – Yes (on previous analysis)	Yes
XXX	Package	Leakage	Yes	Yes	Yes
ххх	Package	Leakage	NA	Yes	Yes
XXX	Package		Yes	NA	Yes
XXX	Package	Short	NA	Yes	Yes (+)
XXX	Package	Short	NA	Yes	Yes (+)
ххх	Package	Short	NA	Yes – No	Yes (+)
ххх	Die	Leakage	No	No	Yes



Improvement of SNR by lock-in amplifier is demonstrated by separating signal and noise.

Digital lock-in is confirmed to be useful for stability, accuracy, flexibility, better signal quality as well as time resolved imaging

- Further possibility using phase information for new physical information such as layer information
- Thermal lock-in is demonstrated being useful tool to improve SNR and higher sensitivity on Themos system.
- Localize real heat source using phase information



- Package analysis using Thermal emission microscope
- (Themos mini)
- 2009/01/16 reported by Yoshiyuki Yokoyama @HPD
- This experiment is done at HPD to investigate the Themos capability to detect signal at package level without opening a device.
- First steps for stacked devices analysis ?...



Equipment


- THEMOS mini with Lock-In
- IC polisher
- Xray- micro focus system L9631
- Flat panel sensor for X-ray C7921-09

Sample


- Microprocessor (HITACHI H8)
- Front side / Chip size 30mmx30mm)
- 5V apply at line









1.1.2 X ray image (Front side E=80keV)



1.2 Evaluation with Themos


There is a cross hair marked on sample surface. Based on the cross hair point, we overlay the Themos pattern image + thermal image + X-ray image. How to align X-ray image and Themos pattern image shall be determined separately.






In the X-ray image, we can not see Si, but can see bonding wires. Thermal signal is observed around bonding wire area, which leads the guess that there may be something wrong under Si. Thermal signal is not round but looks like having a tail toward right direction

Open the package from backside for further investigation.




ST-NXP Wireless

WMM, C&P Grenoble FA LAB



ST-NXP Wireless

WMM, C&P Grenoble FA LAB



Thermal signal is observed around bonding part on Si. There is another thermal signal observed at left side of large one. We guess this small spot causes a tail in the signal we observed on the device surface.



Note: this report which results from a failure analysis performed in good faith by ST-NXP Wireless solely to help the Customer understand the origin and cause of the problem. It enables the Customer and ST-NXP Wireless to discuss in an amicable manner a mutually acceptable remedial and technical action plan. This report does not imply for ST-NXP Wireless expressly or implicitly any contractual obligations other than as set forth in ST-NXP Wireless General Terms and Conditions of Sale. This report and its contents shall not be disclosed to a third party without previous written agreement from ST-NXP Wireless.

